BWA Tower Estimate from 19Sep2018 Dixon Engineering Inspection

		Categorization of Estimated Costs								
						Minimal Maintenance				ce
#	What	Est Cost	Painting	E	inhance		Repair	Safety	١	/andal
1	Exterior recoat repaint with containment	\$ 180,000	\$ 180,000							
2	Wet interior repaint	\$ 30,000	\$ 30,000							
3	Caulk roof lap seams	\$ 1,000				\$	1,000			
4	Balcony opening	\$ 5,000				\$	5,000			
5	Balcony kick plate	\$ 4,000				\$	4,000			
6	Roof handrail	\$ 10,000						\$ 10,000		
7	Overflow pipe	\$ 8,000		\$	8,000					
8	Overflow splash pad	\$ 2,000		\$	2,000					
9	30 inch roof hatch	\$ 3,000				\$	3,000			
10	Frost-free roof vent	\$ 6,000		\$	6,000					
11	Step-off platform and sidewall ladder	\$ 10,000						\$ 10,000		
12	Leg ladder	\$ 10,000						\$ 10,000		
13	Wet interior ladder	\$ 10,000						\$ 10,000		
14	Vandal guard on leg ladder	\$ 2,000							\$	2,000
15	Vandal plates on double lattice legs	\$ 6,000							\$	6,000
16	Fill pipe deflector plate	\$ 1,000		\$	1,000					
	Sub total	\$ 288,000	\$ 210,000	\$	17,000	\$	13,000	\$ 40,000	\$	8,000
71	Eng. and Contingencies - 14.58%	\$ 42,000	72.9%		5.9%		4.5%	13.9%		2.8%
	Total	\$ 330,000								

New tower - 50K gallon	\$ 600,000
Old tower demolition	\$ 30,000